

# Illustrated part list IPL update

## Instruction

### Handheld; Husqvarna Forest & Garden

#### Husqvarna



*Product Name(s)*

540iXP, 540iXP Bluetooth, 540iXPG

**Description of change**

Improvement of chassis and the microswitch position.

The microswitch holder is adjusted to prevent it from sliding too far down in its seat. This can cause the trigger to remain in released position and the chainsaw will incorrectly act as if the brake is activated and will not be able to run.

*Comments*

Fully interchangeable.

*Introduced from*

<b>Serial number / Date</b>	<b>Remark</b>
November 22, 2022	<b>Start of production</b>

*IPL updates*

<b>Page Title</b>	<b>Ref. no</b>	<b>New part no</b>	<b>Name</b>	<b>Excl. part no.</b>	<b>Remark</b>
Chassis	2	594 92 92-02	Chassis	594 92 92-01	